


No. 511 - UNIVERSAL SHEET WITH SBR BINDER



Description: A general service chrysolite fiber sheet, SBR binder.

Service: Saturated steam, water, brine, mild acids, alkalis, and air.

Temperature Limit: -40°F to 650°F.

Pressure Limit: 600 PSI.

Length: 59" x 63", Larger sizes available upon request.

Non-Stock, Special Order.

Part #	Size	ISSA #
511-164	1/64"	811001
511-132	1/32"	811002
511-116	1/16"	811004
511-332	3/32"	811005
511-180	1/8"	811006
511-316	3/16"	--
511-140	1/4"	--

No. 511S - SEVERE SERVICE WITH SBR BINDER



Description: A severe service chrysolite fiber sheet, SBR binder. Recommended for high pressure steam and high temperature steam.

Service: Saturated steam, water, brine, mild acids, alkalis, air, and most chemicals.

Temperature Limit: -40°F to 1100°F.

Pressure Limit: 3100 PSI.

Length: 59" x 63", Larger sizes available upon request.

Non-Stock, Special Order.

Part #	Size	ISSA #
511S-164	1/64"	811012
511S-132	1/32"	811014
511S-116	1/16"	811015
511S-332	3/32"	811016
511S-180	1/8"	811018