

POLLY PIGS - INDUSTRIAL PIPELINE CLEANERS



Part #:	Description	Application
SBD	Scarlet Bare Durofoam	Heavy wiping and dewatering
SSS	Scarlet Single Spiral	Heavy wiping
SCC	Scarlet Criss-Cross	Heavy cleaning and dewatering
SCC-WB	Scarlet Criss-Cross Wire Brush	Heavy scraping
SCC-SC	Scarlet Criss-Cross Silicon Carbide	Heavy scraping
SCC-T	Scarlet Criss-Cross Turning	Heavy cleaning and dewatering
SCC-WB-T	Scarlet Criss-Cross Wire Brush Turning	Heavy scraping
SCC-SC-T	Scarlet Criss-Cross Silicon Carbide Turning	Heavy scraping
RBS	Red Bare Squeegee	Regular wiping and dewatering
RSS	Red Single Spiral	Regular wiping
RCC	Red Criss-Cross	Regular cleaning and dewatering
RCC-WB	Red Criss-Cross Wire Brush	Regular scraping
RCC-SC	Red Criss-Cross Silicon Carbide	Regular scraping
RCC-T	Red Criss-Cross Turning	Regular cleaning and dewatering
RCC-WB-T	Red Criss-Cross Wire Brush Turning	Regular scraping
RCC-SC-T	Red Criss-Cross Silicon Carbide Turning	Regular scraping
YBS	Yellow Bare Swab	Drying
YBS-B	Yellow Bare Swab Bullet	Drying
YCC	Yellow Criss-Cross	Light cleaning
YCC-SC	Yellow Criss-Cross Silicon Carbide	Light scraping
YCC-T	Yellow Criss-Cross Turning	Light cleaning
YCC-SC-T	Yellow Criss-Cross Silicon Carbide Turning	Light scraping

Notes:

- **Density:** Scarlet = 8 lbs. / cu. ft.; Density of Red = 5 lbs. / cu. ft.; Density of Yellow = 2 lbs. / cu. ft..
- When inquiring and/or ordering, please specify size and type.
- Special application polly pigs are also available, upon request.